

Safety Rules for Hot Work



✓ Do

- ✓ Obtain training on the risks and ways to mitigate them before performing the work.
- ✓ Use personal protective equipment, such as safety shoes, an apron, gloves, and a safety helmet.
- ✓ Ensure that the work environment and pathways are clear of obstacles and hazardous or flammable materials, and that the escape and emergency routes are clear and accessible.
- ✓ Ensure that all employees are familiar with the procedures in case of a fire and know the location of fire extinguishing and emergency equipment.
- ✓ Ensure that a special work permit is obtained for welding, polishing, and grinding work, and take all required safety precautions.
- ✓ Wash hands with soap and water at the end of the work and before eating, drinking, or smoking.

✗ Don't.

- ✗ Do not perform work without proper training on the risks, the method of execution, and the necessary means, materials, and tools for its execution.
- ✗ Do not operate equipment without appropriate training.
- ✗ Do not block access to escape routes, fire extinguishing equipment, or the main power switch.
- ✗ Do not work alone in the work area; ensure that another person is present in case of an emergency.
- ✗ Do not work in confined spaces unless all necessary measures to mitigate risk have been taken.
- ✗ Do not attempt to extinguish a large fire alone. Declare the fire to warn workers and call for assistance.

